PRINTED: 04/24/2007 DEPARTMENT OF HEALTH AND HUMAN SERVICES FORM APPROVED CENTERS FOR MEDICARE & MEDICAID OMB NO. 0938-0391 STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING 01 - MAIN BUILDING 01 B. WING 295044 04/10/2007 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 1950 BARING BLVD **HEARTHSTONE OF NORTHERN NEVADA SPARKS, NV 89434** SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETION (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE **PRÉFIX** REGULATORY OR LSC IDENTIFYING INFORMATION) DATE TAG CROSS-REFERENCED TO THE APPROPRIATE TAG DEFICIENCY) **INITIAL COMMENTS** K 000 K 000 This Statement of Deficiencies was generated as a result of the Life Safety Code (LSC) survey conducted at your facility on 4/9/07 and 4/10/07. Your facility was surveyed using Chapter 19, EXISTING Health Care Occupancies, of the 2000 Edition of the National Fire Protection Association's (NFPA) 101, Life Safety Code. The findings and conclusions of any investigation by the Health Division shall not be construed as RECEIVED prohibiting any criminal or civil investigations. actions or other claims for relief that may be MAY 0 4 2007 available to any party under applicable federal, state, or local laws. BUREAU OF LICENSURE AND CERTIFICATION CARSON CITY, NEVADA K 018 NFPA 101 LIFE SAFETY CODE STANDARD K 018 SS=D Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas are substantial doors, such as K 018 those constructed of 1% inch solid-bonded core wood, or capable of resisting fire for at least 20 minutes. Doors in sprinklered buildings are only Resident room door # 107 was required to resist the passage of smoke. There is adjusted and tested and found to shut no impediment to the closing of the doors. Doors properly. are provided with a means suitable for keeping the door closed. Dutch doors meeting 19.3.6.3.6 Residents residing in the facility have are permitted. 19.3.6.3 the potential to be affected by this practice. Roller latches are prohibited by CMS regulations in all health care facilities. Maintenance Department will inspect doors monthly for proper closure.

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Delnam. Lota Por

DON

514107

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID RVICES

PRINTED: 04/24/2007 FORM APPROVED OMB NO. 0938-0391

(X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER COMPLETED A BUILDING 01 - MAIN BUILDING 01 B WING 295044 04/10/2007 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 1950 BARING BLVD **HEARTHSTONE OF NORTHERN NEVADA SPARKS, NV 89434** SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (X5) COMPLETION (EACH DEFICIENCY MUST BE PRECEDED BY FULL **PREFIX** (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE DATE TAG TAG DEFICIENCY) K 018 Continued From page 1 K 018 This STANDARD is not met as evidenced by: Based on observation during the facility tour with the Maintenance Director on 4/9/07 at 10:00am, it was determined the facility failed to ensure all resident room doors would close and latch. Findings include: During the facility tour it was observed that resident room door # 107 would not latch when closed. RECEIVED MAY **0 4** 2007 BUREAU OF LICENSURE AND CERTIFICATION CARSON CITY, NEVADA